



Products for FOD Control

Q: What is FOD and why is FOD control important in a manufacturing environment?



A: In manufacturing, FOD control practices are enforced for quality and safety control purposes. Foreign Object Damage can occur when FOD (Foreign Object Debris) enters a manufacturing area.

Controlling FOD can **prevent damage to equipment and products, future repairs, and even injury or death due to product failure.** Implementing FOD control practices now can help your facility get a jump-start on this new initiative.

Featured Products for FOD Control



Presaturated Wipes

Presaturated Wipes are effective at removing dirt and grime from surfaces including sensitive electronic components.

- Various Saturation Levels & Materials Available.
- Custom Options Available



VISION ESD Wipes

VS50-99 ESD Polyester Wipes help reduce unwanted particulate on surfaces in PCB, SMT, and electronic manufacturing environments.

They are anti-static, lint-free, clean-room processed, and feature carbon core nylon fibers to further enhance their ESD-safe properties.



GREEN MONSTER™

GREEN MONSTER!™ Stencil Wiping Rolls are lint-free, ESD safe, and have a highly effective cleaning surface.

- For DEK, EKRA, MPM, and Panasonic SMT Printers.
- Custom Configurations Available Upon Request



Tacky Traxx

Traxx™ Floor Mats reduce outside dirt and debris from being tracked inside.

- Durable and Smooth Tacky Surface Withstands Foot and Cart Traffic
- Custom Logo Mats Available

Private Label Options Available | Custom Converting Capabilities | Drop Shipping Services Available



Educational Content & News:



860.265.2633 | high-techconversions.com
High-Tech Conversions, Inc. 1699 King Street, Enfield, CT, 06082

